


Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350 $^{\circ}$ C, 50 Watt max. and use a pencil tip.
- 4. Apply some solder to the solder tip of the soldering iron.
- 5. Put tip to wire in solder cup.
- 6. After 1 second bring in solder.
- 7. Heat for 3 seconds longer. Do not heat contact more than 4 seconds in total.
- 8. Remove soldering iron.
- 9. Wait until solder gets rigid again.
- Do not solder adjacent contacts consecutively,
 alternate position within the connector to minimize heat build up.

RECOMMENDED PANEL CUT-OUT



| | THIS DRAWING MAY NOT BE COPIED OR REPRODUCED IN MAY WAY, AND MAY WOT BE PASSED ON TO A THIRD PARTY WITHOUT WRITTEN PERMISSION. WRITTEN PERMISSION. | DO NOT ALTER CAD DRAWING BY HAND | | | | | tolerance | | dim. in mm | scale: material: | 3:1 see sheet 1 | |
|--|---|----------------------------------|------|-------------|------|------|-----------|----------|------------|---|------------------------|---------|
| | | | | | | | | date | name | title: | | |
| | | | | | | | drawn | 13.12.10 | Henneboel | | PANEL CUT-OUT | |
| | | | | | | | appd. | 14.12.10 | Fischer | 1 | D-SUB HD FEMALE 15pos. | |
| | | | | | | | norm | | | with threaded insert and hexlocking screw | | crew |
| | | | | | | | d-old | | | dwg no: DI | | DIN- |
| | | | | | | | | | | 1EV1 A760 | 1 E V 1 A 7 C O | A3 |
| | | | а | Original | | | | | | 15K1A768 | | sh: 2/2 |
| | THIS DRA REPRODU BE PASSE WRITTEN OWNERSH | | rev. | description | date | name | • | | | part no: | SEE SHEET1 | |

D D